

Contents	Page
Foreword	3
Introduction.....	4
1 Scope	5
2 Normative references	5
3 Terms and definitions.....	5
4 Sample properties	5
5 Isothermal entropy change $\Delta s (M, T, H)$	6
5.1 Introduction.....	6
5.2 Brief summary of procedure	6
5.3 Devices.....	6
5.4 Measurement	7
5.5 Calculation of Δs_T	10
6 Isothermal entropy change Δs (measured by DSC).....	11
6.1 Measurement	11
6.2 Calculations of Δs_T	12
7 Adiabatic temperature change ΔT_{ad}	13
7.1 Introduction.....	13
7.2 Brief summary of procedure	13
7.3 Devices.....	14
7.4 Measurement	14
Bibliography	18

Figures

Figure 1 — Scheme for the determination of boundary temperatures for a phase reset during isofield MH measurements	10
Figure 2 — Exemplary temperature-dependent heat capacity measurement for a second-order phase transition with and without an externally applied magnetic field	12
Figure 3 — Temperature-dependent specific entropy calculated from heat capacity measurements (see Figure 2) for a second-order phase transition with and without an externally applied magnetic field	12
Figure 4 — Exemplary adiabatic temperature change measurements for a second-order phase transition a) as well as for a conventional b) and inverse c) first-order phase transition.....	16