

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Symbols and units	6
5 Principle	6
6 Apparatus	6
6.1 General	6
6.2 Constant-temperature enclosure	7
6.3 Heater and sensor elements	7
6.4 Heating circuit	9
6.5 Measurement circuit	9
6.6 Phase-shift measurement device	9
6.7 Devices for measuring the specimen temperature	9
7 Test specimen	10
7.1 Dimensions	10
7.2 Thickness	10
7.3 Specimen-backing plates	10
8 Procedure	10
9 Analysis of results	11
10 Calibration and verification of apparatus and method	12
10.1 Calibration	12
10.2 Verification	12
11 Precision and bias	13
11.1 Uncertainty	13
11.2 Repeatability	13
12 Test report	13
Annex A (informative) Mathematical background to temperature wave analysis	14
Annex B (informative) Typical thermal-diffusivity data for a typical polyimide	15
Annex C (informative) Example of frequency-thickness relationships required for acceptable measurements	16
Annex D (informative) Numerical simulations of the phase shift, ϕ , as a function of k_d and ω	18
Annex E (informative) Examples of uncertainties in thermal-diffusivity measurements	19
Bibliography	20