

# DIN EN 14625:2012-12 (E)

## Ambient air - Standard method for the measurement of the concentration of ozone by ultraviolet photometry

---

<b>Contents</b>		<b>Page</b>
<b>Contents 2</b>		
Foreword .....		4
1 Scope .....		5
2 Normative references .....		6
3 Terms and definitions .....		6
4 Abbreviated terms .....		11
5 Principle .....		11
5.1 General .....		11
5.2 Measuring principle .....		11
5.3 Type approval test .....		12
5.4 Field operation and quality control .....		12
6 Sampling .....		12
6.1 General .....		12
6.2 Sampling location .....		13
6.3 Sampling system .....		13
6.4 Control and regulation of sample flow rate .....		14
6.5 Sampling pump for the manifold .....		14
7 Analyser equipment .....		14
7.1 General .....		14
7.2 Ultraviolet absorption cell .....		15
7.3 Ultraviolet source lamp .....		15
7.4 UV detector .....		15
7.5 Ozone-specific scrubber .....		15
7.6 Switching valve .....		15
7.7 Temperature indicator .....		15
7.8 Pressure indicator .....		15
7.9 Flow rate indicator .....		16
7.10 Sampling pump for the analyser .....		16
7.11 Internal ozone span source .....		16
7.12 Particle filter .....		16
8 Type approval of ultraviolet photometric ozone analysers .....		16
8.1 General .....		16
8.2 Relevant performance characteristics and performance criteria .....		17
8.3 Design change .....		18
8.4 Procedures for determination of the performance characteristics during the laboratory test .....		19
8.5 Determination of the performance characteristics during the field test .....		30
8.6 Type approval and uncertainty calculation .....		33
9 Field operation and ongoing quality control .....		34
9.1 General .....		34
9.2 Suitability evaluation .....		34

9.3	Initial installation .....	36
9.4	Ongoing quality assurance/quality control .....	37
9.5	Calibration of the analyser .....	38
9.6	Checks .....	40
9.7	Maintenance .....	44
9.8	Data handling and data reports .....	44
9.9	Measurement uncertainty .....	45
10	Expression of results .....	45
11	Test reports and documentation .....	45
11.1	Type approval test .....	45
11.2	Field operation .....	47
Annex A (normative) Test of lack of fit .....		48
Annex B (informative) Sampling equipment .....		50
Annex C (informative) Ultraviolet photometric analyser .....		52
Annex D (informative) Manifold testing equipment .....		54
Annex E (normative) Type approval .....		56
Annex F (informative) Calculation of uncertainty in field operation at the hourly alert threshold value .....		75
Annex G (informative) Calculation of uncertainty in field operation at the 8-hour target value .....		83
Annex H (informative) Significant technical changes .....		93
Bibliography .....		94